

# PASSIVE RESTRAINT SYSTEM INSPECTION

ABC123

Entire Article  
2000 Chevrolet Camaro

## ARTICLE BEGINNING

### GENERAL INFORMATION

Air Bag/SRS Component Inspection & Replacement Tables

General Motors

## INTRODUCTION

When a vehicle equipped with passive restraint system has been involved in a collision, certain systems and components must be inspected and or replaced regardless of whether or not the air bag has deployed. Follow the manufacturer's guidelines provided in this article.

**WARNING:** Accidental air bag deployment is possible. Personal injury may result. Avoid area near steering wheel and instrument panel even if air bags have deployed. Dual-stage air bag modules may be present that could contain an undeployed stage. When disposing of a deployed dual-stage air bag, always treat it as a "live" module. See appropriate AIR BAG RESTRAINT SYSTEM articles in the ACCESSORIES/SAFETY EQUIPMENT section.

## GENERAL MOTORS (1988-01)

### AIR BAG APPLICATION

#### APPLICATION

Make/Model	Year	Location	Table
Achieva	1998	D/P	GM-14
	1996-97	D/P	GM-1
	1994-95	DS	GM-2
Alero	1999-01	D/P	GM-14
Allante	1993	DS	GM-5
	1990-92	DS	GM-6
Astro	1997-01	D/P	GM-14
	1996	D/P	GM-1
	1993-95	DS	GM-2
Aurora			
Dual Stage	2001	D/P2, SI	GM-22
Single Stage	2001	D/P, SI	GM-22
	1996-99	D/P	GM-1
	1995	D/P	GM-2
Aztek	2001	D/P, SI	GM-14
Beretta	1993-96	DS	GM-2
	1991-92	DS	GM-5
Blazer	1998-01	D/P	GM-15
	1995-97	DS	GM-2

**PASSIVE RESTRAINT SYSTEM INSPECTION**

**ABC123**

**Entire Article**  
2000 Chevrolet Camaro

Bonneville	2001	D/P2, SI	GM-22
	2000	D/P, SI	GM-20
	1997-99	D/P	GM-16
	1994-96	D/P	GM-2
Bonneville SE-SSE	1992-93	DS	GM-2
Bonneville SSE-SSEi	1992-93	D/P	GM-2
Bravada	1998-01	D/P	GM-15
	1996-97	DS	GM-2
C-K Pickup	1994-96	DS	GM-2
	1997-00	D/P	GM-15
	1995-96	DS	GM-2
Camaro	1997-01	D/P	GM-14
	1996	D/P	GM-1
	1993-95	D/P	GM-2
	1990-92	DS	GM-5
Caprice	1995-96	D/P	GM-3
	1994	D/P	GM-2
	1993	DS	GM-2
	1991-92	DS	GM-6
Catera	1997-01	D/P, SI	GM-17
Cavalier	1998-01	D/P	GM-14
	1996-97	D/P	GM-1
	1995	D/P	GM-3
Century	2000-01	D/P, SI	GM-20
	1997-99	D/P	GM-14
	1993-96	DS	GM-2
Chevy Van			
Early Design	1994-96	DS	GM-2
	1997-00	D/P	GM-15
	1995-96	DS	GM-2
New Design	1997-98	D/P	GM-16
Concours	1994-96	D/P	GM-2
Corsica	1993-96	DS	GM-2
	1991-92	DS	GM-5
Corvette	1997-01	D/P	GM-14
	1994-96	D/P	GM-3
	1993	DS	GM-2
	1991-92	DS	GM-5
	1990	DS	GM-7
Custom Cruiser	1991-92	DS	GM-6
Cutlass	1997-99	D/P	GM-14
Cutlass Ci era	1993-96	DS	GM-2
Cutlass Supreme	1997	D/P	GM-14
	1995-96	D/P	GM-4
	1994	DS	GM-2
Delta 88	1988-91	DS	GM-8
Devil e	2000-01	D/P, SI	GM-21
	1994-96	D/P	GM-2
	1993	DS	GM-2
Devil e-Concours			
D'El egance	1997-99	D/P, SI	GM-18
Devil e-Fl eetwood	1992	DS	GM-2

**PASSIVE RESTRAINT SYSTEM INSPECTION**

**ABC123**

**Entire Article**  
2000 Chevrolet Camaro

Eighty Eight-Royal -LS	1989-91	DS	GM-6
	1997-99	D/P	GM-16
	1994-96	D/P	GM-2
	1993	DS	GM-2
	1992	DS	GM-6
El dorado	2001	D/P	GM-23
	1997-00	D/P	GM-18
	1993-96	D/P	GM-2
	1990-92	DS	GM-6
Envoy	1998-00	D/P	GM-15
Escalade	2000	D/P	GM-15
Express Van	1997-01	D/P	GM-16
	1996	D/P	GM-1
Firebird	1997-01	D/P	GM-14
	1996	D/P	GM-1
	1993-95	D/P	GM-2
	1990-92	DS	GM-5
Fleetwood Brougham	1993-96	D/P	GM-2
Grand Am	1998-01	D/P	GM-14
	1996-97	D/P	GM-1
	1994-95	DS	GM-2
Grand Prix	1997-01	D/P	GM-14
	1994-96	D/P	GM-4
Impala	2001	D/P2, SI	GM-20
	2000	D/P, SI	GM-20
Impala SS	1995-96	D/P	GM-3
	1994	D/P	GM-2
Intrigue	1998-01	D/P	GM-14
Jimmy	1998-01	D/P	GM-15
	1995-97	DS	GM-2
LeSabre	2001	D/P2, SI	GM-22
	2000	D/P, SI	GM-20
	1997-99	D/P	GM-16
	1994-96	D/P	GM-2
	1993	DS	GM-2
	1992	DS	GM-6
Lumina	1997-00	D/P	GM-14
	1995-96	D/P	GM-4
Lumina APV	1994-96	DS	GM-2
LSS	1997-99	D/P	GM-16
	1996	D/P	GM-2
Malibu	1997-01	D/P	GM-14
Metro	1998-01	D/P	GM-9
	1995-97	D/P	GM-9
	1993	DS	GM-9
	1990-92	DS	GM-11
Montana	1999-01	D/P, SI	GM-14
Monte Carlo	2001	D/P2, SI	GM-20
	2000	D/P, SI	GM-20
	1997-99	D/P	GM-14
	1995-96	D/P	GM-4

**PASSIVE RESTRAINT SYSTEM INSPECTION**

**ABC123**

**Entire Article**  
2000 Chevrolet Camaro

Ninety Eight			
Regency	1994-96	D/P	GM-2
	1993	DS	GM-2
	1991-92	DS	GM-6
	1989-90	DS	GM-8
Park Avenue	2000-01	D/P, SI	GM-20
Park Avenue-Ultra	1997-99	D/P	GM-19
	1994-96	D/P	GM-2
	1993	DS	GM-2
	1991-92	DS	GM-6
Pri z m	1998-01	D/P, SI	GM-17
	1994-97	D/P	GM-10
	1993	DS	GM-10
Rally-Vandura	1994-96	DS	GM-2
Regency	1997-98	D/P	GM-16
Reatta	1990-91	DS	GM-6
Regal	2000-01	D/P, SI	GM-20
	1997-99	D/P	GM-14
	1995-96	D/P	GM-4
	1994	DS	GM-2
Riviera	1996-99	D/P	GM-1
	1995	D/P	GM-2
	1990-93	DS	GM-6
Roadmaster	1995-96	D/P	GM-3
	1994	D/P	GM-2
	1993	DS	GM-2
	1991-92	DS	GM-6
S10 Pickup	1998-01	DS	GM-15
	1995-97	DS	GM-2
Safari	1997-01	DS	GM-14
	1996	D/P	GM-1
	1993-95	DS	GM-2
Saturn Coupe	1995-99	D/P	GM-12
	1992-94	DS	GM-13
Saturn L-Series	2001	D/P, HI	GM-12
	2000	D/P	GM-12
Saturn S-Series	2001	D/P, HI	GM-12
	2000	D/P	GM-12
Saturn Sedan	1995-99	D/P	GM-12
	1992-94	DS	GM-13
Saturn Wagon	1995-99	D/P	GM-12
	1993-94	DS	GM-13
Savana	1997-01	D/P	GM-16
	1996	D/P	GM-1
Seville	1998-01	D/P, SI	GM-21
	1997	D/P	GM-18
	1993-96	D/P	GM-2
	1990-92	DS	GM-6
Sierra	2001	D/P	GM-20
	1997-00	D/P	GM-15
	1995-96	DS	GM-2
Silhouette	1999-01	D/P, SI	GM-14

**PASSIVE RESTRAINT SYSTEM INSPECTION**

**ABC123**

**Entire Article**  
2000 Chevrolet Camaro

	1997-98	D/P	GM-14
	1994-96	DS	GM-2
Si l verado	2001	D/P	GM-20
	1999-00	D/P	GM-15
	1995-96	DS	GM-2
Skyl ark	1998	D/P	GM-14
	1996-97	D/P	GM-1
	1994-95	DS	GM-2
Sonoma	1998-01	D/P	GM-15
	1995-97	DS	GM-2
Sportvan	1994-96	DS	GM-2
Storm	1993	DS	GM-9
	1990-92	DS	GM-11
Suburban	2000-01	D/P, SI	GM-20
	1997-99	D/P	GM-15
	1995-96	DS	GM-2
Sunfi re	1998-01	D/P	GM-14
	1996-97	D/P	GM-1
	1995	D/P	GM-3
Tahoe	2000-01	D/P, SI	GM-20
	1997-99	D/P	GM-15
	1995-96	DS	GM-2
Toronado	1990-92	DS	GM-6
Tracker	1998-01	D/P	GM-9
	1996-97	D/P	GM-9
Venture	1999-01	D/P, SI	GM-14
	1997-98	D/P	GM-14
Trans Sport	1997-98	D/P	GM-14
	1994-96	DS	GM-2
Yukon, Yukon XL	2000-01	D/P, SI	GM-20
	1997-99	D/P	GM-15
	1995-96	DS	GM-2

D/P - Dri ver' s & Passen ger' s Si de.  
 D/P2 - Dri ver' s & Passen ger' s Si de (Dual -Stage).  
 DS - Dri ver' s Si de.  
 HI - Head Impact.  
 KI - Knee Impact.  
 SI - Si de Impact.  
 PS2 - Passen ger' s Si de (Dual -Stage).  
 AAA

**INSPECTION PROCEDURES**

GM-1  
 UAA

3	Acti on	3	Component or System	3
3	Repl ace After	3 *	Ai r bag modul e(s)	3
3	Depl oyment	3 *	Forward di scri mi nati ng sensor (1)	3
3		3 *	Sen sing & Di agnosti c Modul e (SDM)	3
3		3 *	Sen sors in area of acci dent damage (2)	3

PASSIVE RESTRAINT SYSTEM INSPECTION

ABC123

Entire Article
2000 Chevrolet Camaro

3 \* Instrument panel magnesium beam (3)
3 Inspect & If 3 \* Forward discriminating sensor (1)
3 Damaged Replace 3 \* Instrument panel braces (3)
3 Component (Even If 3 \* Instrument panel magnesium beam (4)
3 Air Bag Did Not 3 \* Instrument panel steering column
3 Deploy) 3 reinforcement plate
3 \* Knee bolsters & mounting points (4)
3 \* Seat belts & mounting points
3 \* Sensors in area of accident damage (without
3 deployment) (2)
3 \* SIR coil assembly
3 \* Steering column (4)
3 Comments 3 Any sensor which the Sensing & Diagnostic
3 Module (SDM) indicates as bad must be replaced.
3 If any components are damaged or bent, they
3 must be replaced. SIR wiring can be repaired
3 following manufacturer's instructions. On
3 Chevrolet Express Van & GMC Savana only, check
3 for excessive gaps between dash trim panels
3 following manufacturer's instructions. If gaps
3 are excessive, replace instrument panel
3 magnesium beam.
3(1) - Except Camaro, Firebird and 1996-99 Aurora and Rivera.
3(2) - 1996-98 Aurora and Riviera only.
3(3) - Chevrolet Express Van and GMC Savana only.
3(4) - If damaged, also replace instrument panel magnesium beam
3 on Chevrolet Express Van and GMC Savana only.

GM-2

Action Component or System
3 Replace After 3 \* Air bag module(s)
3 Deployment 3 \* Sensors in area of accident damage
3 Inspect & If 3 \* Instrument panel braces
3 Damaged Replace 3 \* Instrument panel steering column
3 Component (Even If 3 reinforcement plate
3 Air Bag Did Not 3 \* Knee bolster and mounting points
3 Deploy) 3 \* Seat belts & mounting points
3 \* Sensors in area of accident damage (without
3 deployment)
3 \* SIR coil assembly
3 \* Steering column
3 \* Steering wheel (1)
3 Comments 3 Any sensor which the Diagnostic Energy Reserve
3 Module (DERM) or Sensing & Diagnostic Module

PASSIVE RESTRAINT SYSTEM INSPECTION

ABC123

Entire Article
2000 Chevrolet Camaro

(SDM) indicates as bad must be replaced. If any components are damaged or bent, they must be replaced. SIR wiring can be repaired following manufacturer's instructions.

(1) - 1995 Aurora, Bonneville, Concours, DeVille, Eighty Eight, Eldorado, Lesabre, Ninety Eight, Park Avenue, Riviera, Seville, and 1995-96 Fleetwood.

GM-3

Table with 3 columns: Action, Component or System, and a blank column. Rows include: Air bag module(s), All sensors, Instrument panel braces, Instrument panel steering column reinforcement plate, Knee bolster and mounting points, Seat belts & mounting points, Sensors in area of accident damage (without deployment), SIR coil assembly, Skid plate-skid bar assembly (1), Steering column, Steering wheel (2).

Comments Any sensor which the Diagnostic Energy Reserve Module (DERM) indicates as bad must be replaced. If any components are damaged or bent, they must be replaced. SIR wiring can be repaired following manufacturer's instructions.

(1) - 1996 Corvette only.
(2) - Cavalier, Corvette and Sunfire only.

GM-4

Table with 3 columns: Action, Component or System, and a blank column. Rows include: Air bag module(s), Anti-theft module (if equipped), Anti-theft module bracket (if equipped), Instrument panel braces, Instrument panel steering column reinforcement plate, Knee bolster and mounting points, Seat belts & mounting points.

**PASSIVE RESTRAINT SYSTEM INSPECTION**

**ABC123**

**Entire Article**  
2000 Chevrolet Camaro

```

3          3 * SIR coil assembly          3
3          3 * Steering wheel              3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA`
3 Comments          3 Any sensor which the Sensing & Diagnostic          3
3          3 Module (SDM) indicates as bad must be          3
3          3 replaced. If any components are damaged or          3
3          3 bent, they must be replaced. SIR wiring can be          3
3          3 repaired following manufacturer's instructions.          3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAU
    
```

GM-5

```

UAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA;
3      Action          3          Component or System          3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA`
3 Replace After          3 * Air bag module          3
3 Deployment          3 * Arming sensor          3
3          3 * Forward discriminating sensor          3
3          3 * Passenger compartment discriminating sensor          3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA`
3 Inspect & If          3 * Diagnostic Energy Reserve Module (DERM)          3
3 Damaged Replace          3 * Instrument panel braces          3
3 Component (Even If          3 * Instrument panel steering column          3
3 Air Bag Did Not          3 reinforcement plate          3
3 Deploy)          3 * Knee bolster & mounting points          3
3          3 * Seat belts & mounting points          3
3          3 * SIR coil assembly          3
3          3 * Steering column          3
3          3 * Steering wheel          3
3          3 * Wiring harness          3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA`
3 Comments          3 If any components are damaged or bent, they          3
3          3 must be replaced. SIR wiring can be repaired          3
3          3 following manufacturer's instructions.          3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA`
3(1) - Beretta and Corsica only.          3
3(2) - Corvette only.          3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAU
    
```

GM-6

```

UAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA;
3      Action          3          Component or System          3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA`
3 Replace After          3 * Air bag module          3
3 Deployment          3 * Dual sensor          3
3          3 * Forward discriminating sensor          3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA`
3 Inspect & If          3 * Instrument panel braces          3
3 Damaged Replace          3 * Instrument panel lower trim (1)          3
3 Component (Even If          3 * Instrument panel steering column          3
3 Air Bag Did Not          3 reinforcement plate          3
3 Deploy)          3 * Knee bolster & mounting points          3
3          3 * Seat belts & mounting points          3
    
```

**PASSIVE RESTRAINT SYSTEM INSPECTION**

**ABC123**

**Entire Article**  
2000 Chevrolet Camaro

- 3 \* SIR coil assembly 3
- 3 \* Steering column 3
- 3 \* Steering wheel 3
- 3 \* Wiring harness 3

Comments 3 If any components are damaged or bent, they  
3 must be replaced. SIR wiring can be repaired  
3 following manufacturer's instructions.

(1) - LeSabre and Park Avenue only. 3  
U

**GM-7**

U  
3 Action 3 Component or System 3

- 3 \* Air bag module 3
- 3 \* Diagnostic Energy Reserve Module (DERM) 3
- 3 \* Front discrimination sensors 3
- 3 \* SIR coil assembly 3

Inspect & If 3 \* Instrument panel braces 3  
3 Damaged Replace 3 \* Instrument panel steering column 3  
3 Component (Even If 3 reinforcement plate 3

- 3 \* Knee bolster & mounting points 3
- 3 \* Seat belts & mounting points 3
- 3 \* SIR coil assembly 3
- 3 \* Steering column 3
- 3 \* Steering wheel 3
- 3 \* Wiring harness 3

Comments 3 If any components are damaged or bent, they  
3 must be replaced. SIR wiring can be repaired  
3 following manufacturer's instructions.

U

**GM-8**

U  
3 Action 3 Component or System 3

- 3 \* Air bag module 3
- 3 \* Arming sensor 3
- 3 \* Passenger Compartment Sensor-Diagnostic 3  
3 Module (PCSDM) or SIR control module 3

Inspect & If 3 \* Knee bolster & mounting points 3  
3 Damaged Replace 3 \* Seat belts & mounting points 3  
3 Component (Even If 3 \* SIR coil assembly 3

- 3 \* Steering column 3
- 3 \* Wiring harness 3

Comments 3 If any components are damaged or bent, they 3





### PASSIVE RESTRAINT SYSTEM INSPECTION

ABC123

Entire Article  
2000 Chevrolet Camaro

GM-13

U	AA	C
3	Action	3
		Component or System
	A	AA
3	Replace After	3
	3 * Air bag module	3
3	Deployment	3
	3 * Sensors in area of accident damage	3
	A	AA
3	Inspect & If	3
	3 * Any sensor which DERM indicates as bad	3
3	Damaged Replace	3
	3 * Diagnostic Energy Reserve Module (DERM)	3
3	Component (Even If	3
	3 * Instrument panel moulding attachments	3
3	Air Bag Did Not	3
	3 * Knee bolster	3
3	Deploy)	3
	3 * Resistor module	3
	3 * Seat belts & mounting points	3
	3 * Sensors in area of accident damage (without	3
	deployment)	3
	3 * SIR coil assembly	3
	3 * Steering column	3
	3 * Steering wheel	3
	A	AA
3	Comments	3
	3 If any components are damaged or bent, they	3
	3 must be replaced.	3
	U	AA

GM-14

U	AA	C
3	Action	3
		Component or System
	A	AA
3	Replace After	3
	3 * Air bag module(s)	3
3	Deployment	3
	3 * Front sensor (1)	3
	3 * Sensing & Diagnostic Module (SDM)	3
	3 * Sensors in area of accident damage	3
	3 * Theft deterrent module (2)	3
	3 * Side impact inflator module (3)	3
	3 * Side impact sensor (3)	3
	A	AA
3	Inspect & If	3
	3 * Instrument panel braces & brackets	3
3	Damaged Replace	3
	3 * Instrument panel cross car beam (4)	3
3	Component (Even If	3
	3 * Instrument panel knee bolsters	3
3	Air Bag Did Not	3
	3 * Seat belts & mounting points	3
3	Deploy)	3
	3 * Seats & seat mounting points	3
	3 * Steering column	3
	3 * Steering wheel module coil (SIR coil)	3
	A	AA
3	Comments	3
	3 If any components are damaged or bent, they	3
	3 must be replaced.	3
	U	AA
	3(1) - 2001 Astro and Safari.	3
	3(2) - Cutlass Supreme, Lumina and Monte Carlo only.	3
	3(3) - On side of impact.	3
	3(4) - 2001 models only.	3
	U	AA

PASSIVE RESTRAINT SYSTEM INSPECTION

ABC123

Entire Article  
2000 Chevrolet Camaro

GM-15

Action	Component or System
Replace After Deployment	* Air bag module(s)
	* Front end discriminating sensor
	* Sensing & Diagnostic Module (SDM)
	* Sensors in area of accident damage
	* Side impact inflator module(s) (1), (2)
	* Side impact sensor (1), (2)
Inspect & If Damaged Replace Component (Even If Air Bag Did Not Deploy)	* Instrument panel braces & brackets
	* Instrument panel knee bolsters
	* Seat belts & mounting points
	* Steering column
	* Steering wheel module coil (SIR coil)
	* Sensors in area of accident damage (without deployment)
Comments	If any components are damaged or bent, they must be replaced.
	(1) - If equipped.
	(2) - On side of impact.

GM-16

Action	Component or System
Replace After Deployment	* Air bag module(s)
	* Sensing & Diagnostic Module (SDM)
	* Instrument panel magnesium beam (1)
	* Sensors in area of accident damage
Inspect & If Damaged Replace Component (Even If Air Bag Did Not Deploy)	* Front end discriminating sensor
	* Instrument panel braces & brackets
	* Instrument panel knee bolsters (2)
	* Instrument panel steering column reinforcement plate (3)
	* Seat belts & mounting points
	* Seats & seat mounting points
	* Sensors in area of accident damage (without deployment)
	* Steering column (2)
	* Steering wheel module coil (SIR coil)
Comments	If any components are damaged or bent, they must be replaced. On Chevrolet Express Van & GMC Savana only, check for excessive gaps between dash trim panels following

**PASSIVE RESTRAINT SYSTEM INSPECTION**

**ABC123**

**Entire Article  
2000 Chevrolet Camaro**

3 manufacturer's instructions. If gaps are 3  
 3 excessive, replace instrument panel magnesium 3  
 3 beam. 3  
 ÀAAÁ´  
 3(1) - Chevrolet Express Van and GMC Savana only. 3  
 3(2) - If damaged, also replace instrument panel magnesium beam 3  
 3 on Chevrolet Express Van and GMC Savana only. 3  
 3(3) - Bonneville, Eighty Eight, LeSabre, LSS and Regency only. 3  
 ÀAAU

**GM-17**

ÚAAÇ  

3 Action	3 Component or System	3
3 Replace After	3 * Air bag module(s)	3
3 Deployment	3 * Front end discriminating sensor (1)	3
	3 * Sensing & Diagnostic Module (SDM)	3
	3 * Seat Belt Pretensioners	3
	3 * Sensors in area of accident damage	3
	3 * Side impact inflator module(s) (2)	3
	3 * Side impact sensor & mounting bracket (2)	3
3 Inspect & If	3 * Door harness, door seal & seat (2)	3
3 Damaged Replace	3 * Instrument panel braces & brackets	3
3 Component (Even If	3 * Instrument panel cross car beam (3)	3
3 Air Bag Did Not	3 * Instrument panel steering column	3
3 Deploy)	3 reinforcement plate	3
	3 * Knee bolster & mounting points	3
	3 * Seats & seat mounting points	3
	3 * Seat belts & mounting points	3
	3 * Seat belt pretensioners	3
	3 * Sensors in area of accident damage (without	3
	3 deployment)	3
	3 * Steering column	3
	3 * Steering wheel module coil (SIR coil)	3
3 Comments	3 If any components are damaged or bent, they	3
3	3 must be replaced.	3
3(1) - 2001 Prizm.		3
3(2) - On side of impact.		3
3(3) - On Prizm and 2001 Catera.		3

ÀAA´  
 ÀAAU

**GM-18**

ÚAAÇ  

3 Action	3 Component or System	3
3 Replace After	3 * Air bag module(s)	3
3 Deployment	3 * Door assembly (1)	3
	3 * Door trim panel (1)	3
	3 * Instrument panel assembly (2)	3

PASSIVE RESTRAINT SYSTEM INSPECTION

ABC123

Entire Article
2000 Chevrolet Camaro

Table with 3 columns: Action, Component or System, and Quantity. Rows include Instrument panel upper trim panel, Sensors in area of accident damage, Side impact inflator module(s) (1), Side Impact Sensing Module (SISM) (1), Front discriminating sensor, Instrument panel braces, Instrument panel knee bolsters & mounting points, Instrument panel mounting points & brackets, Instrument panel steering column reinforcement plate, Passenger side air bag module mounting points, Side impact inflator module(s) mounting points, Side Impact Sensing Module(s) (SISM) mounting points, Seat belts & mounting points, Sensing & Diagnostic Module (SDM), Steering column, Steering wheel module coil (SIR coil), and a Comments section regarding damaged components.

GM-19

Table with 3 columns: Action, Component or System, and Quantity. Rows include Air bag module(s), Instrument panel cross car beam (1), Sensing & Diagnostic Module (SDM) (2), Upper instrument panel pad, Instrument panel braces, Instrument panel cross car beam, Instrument panel knee bolsters & mounting points, Instrument panel mounting points & brackets, Passenger-side air bag module mounting points, Seat belts & mounting points, Sensing & Diagnostic Module (SDM), Steering Column, Steering column support bracket, Steering wheel module coil (SIR coil), and a Comments section regarding damaged components.

**PASSIVE RESTRAINT SYSTEM INSPECTION**

**ABC123**

**Entire Article**  
**2000 Chevrolet Camaro**

3 3 must be replaced. 3  
 ^AA^  
 3(1) - If passenger-side air bag module mounting points are damaged. 3  
 3(2) - If in area of accident damage. 3  
 ^AA^

GM-20

^AA^  
 3 Action 3 Component or System 3  
 ^AA^  
 3 Replace After 3 \* Air bag module(s) 3  
 3 Deployment 3 \* Electronic Frontal Sensor (EFS) (1) 3  
 3 3 \* Front end discriminating sensor (1) 3  
 3 3 \* Sensing & Diagnostic Module (SDM) 3  
 3 3 \* Sensors in area of accident damage 3  
 3 3 \* Side impact inflator module(s) (2), (3) 3  
 ^AA^  
 3 Inspect & If 3 \* Instrument panel braces & brackets 3  
 3 Damaged Replace 3 \* Instrument panel cross car beam 3  
 3 Component (Even If 3 \* Instrument panel steering column 3  
 3 Air Bag Did Not 3 reinforcement plate 3  
 3 Deploy) 3 \* knee bolsters & mounting points 3  
 3 3 \* Seats & seat mounting points 3  
 3 3 \* Seat belts & mounting points 3  
 3 3 \* Sensors in area of accident damage (without 3  
 3 deployment) 3  
 3 3 \* Steering Column 3  
 3 3 \* Steering wheel module coil (SIR coil) 3  
 ^AA^  
 3 Comments 3 If any components are damaged or bent, they 3  
 3 3 must be replaced. 3  
 ^AA^  
 3(1) - 2001 models, if equipped. 3  
 3(2) - On side of impact. 3  
 3(3) - If equipped. 3  
 ^AA^

GM-21

^AA^  
 3 Action 3 Component or System 3  
 ^AA^  
 3 Replace After 3 \* Air bag module(s) 3  
 3 Deployment 3 \* Sensing & Diagnostic Module (SDM) 3  
 3 3 \* Seat belt pretensioners 3  
 3 3 \* Sensors in area of accident damage 3  
 3 3 \* Side impact inflator module(s) (1), (2) 3  
 3 3 \* Side impact sensor & mounting bracket (1) 3  
 ^AA^  
 3 Inspect & If 3 \* Door harness, door seal & seat 3  
 3 Damaged Replace 3 \* Instrument panel braces 3  
 3 Component (Even If 3 \* Instrument panel cross car beam 3  
 3 Air Bag Did Not 3 \* Instrument panel steering column 3

PASSIVE RESTRAINT SYSTEM INSPECTION

ABC123

Entire Article
2000 Chevrolet Camaro

Table with 3 columns: Action, Component or System, and Notes. Includes items like reinforcement plate, knee bolsters, seats, seat belts, steering column, and steering wheel module coil. Includes comments about damaged components and side of impact.

GM-22

Table with 3 columns: Action, Component or System, and Notes. Includes items like Air bag module(s), Electronic Frontal Sensor (EFS), Sensors in area of accident damage, Side impact inflator module(s), and Instrument panel braces & brackets. Includes comments about damaged components and side of impact.

GM-23

Table with 3 columns: Action, Component or System, and Notes. Includes items like Air bag module(s) and Front sensor (front end discriminating sensor).

**PASSIVE RESTRAINT SYSTEM INSPECTION**

**ABC123**

**Entire Article**  
2000 Chevrolet Camaro

```

3                                     3 * Sensing & Diagnostic Module (SDM)                 3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA'
3 Inspect & If                        3 * Instrument panel braces & brackets                 3
3 Damaged Replace                     3 * Instrument panel cross car beam                 3
3 Component (Even If                 3 * Instrument panel steering column                 3
3 Air Bag Did Not                     3 reinfor cement plate                             3
3 Deploy)                             3 * knee bol sters & mounting points                 3
3                                     3 * Seats & seat mounting points                   3
3                                     3 * Seat bel ts & mounting points                   3
3                                     3 * Sensors in area of accident damage (wi thout   3
3                                     3 deployment)                                     3
3                                     3 * Steering Col umn                               3
3                                     3 * Steering wheel module coil (SIR coil)         3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA'
3 Comments                             3 If any components are damaged or bent, they     3
3                                     3 must be replaced. If mounting points are       3
3                                     3 damaged, repair or replace.                   3
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAU

```

**END OF ARTICLE**